	Section	2	Town	Range 24 190) 18								
Contractor (March				I commenced a Survey of Section 24, T. 7, R. 3	CORNER ESTABLISHE	D. Monument.	Device.	WITNESS POINTS OR BEARING TREES.	Mark or Dia. in Inches.	COURSE.	Links Distant.	REMARKS.
				for Nones Van Bushurus	8424-7-5 cm & 24 by & 24 by & 24	store Rtone	+	Beech	24	n 2 E n 2 4 W 8 8 6 E 8 5 0 W	8	broken stour around eme corner on East bank of Nichland creek tree stounds in a gard
	var.			Sanul M. Groman Surveyor Greene County. Per Hrancis M. Sarker Deputy								
	Course.	Point of Beginning,	Chains Distance.	Correcte	ed s.				e e consti			
East- East Nois Wes	t.	S & 24	31.50 39.18 80.35 38.80 46.00 78.70	center 24-7-5 brussys trees standing bank of Richland Creek to E/x n E Went back and found the line from W/x interselved 3° 1'2 links n of half may point '2 mile atoric beaut of Richland Creek 8W24 n 4, 8E								